



Donath Aircraft Services 773.935.9871 jimdonath@donathaircraft.com



Presenting 2003 Falcon 50EX SN 331

This 50EX rises above the rest!

You won't want to miss this outstanding aircraft. Serial Number 331 offers a range of features that make it the most compelling Falcon 50EX available, including:

- Newest Falcon 50EX currently available
- Only three U.S. owners since new
- No known damage history
- 2015 paint and interior (Standard Aero-SPI)
- ADS-B Out (v2)
- WAAS/LPV
- Gogo Biz ATG 4000 WiFi
- Engines and APU enrolled in MSP Gold
- Avionics enrolled in CASP

Schedule your visit today to see this exceptional Falcon 50EX!





Airframe

■ Total Time: 5,180.9 (11/18/19)

■ Landings: 4,370

Engines

Honeywell TFE 731-40 | Enrolled in MSP Gold

	#1 Engine	#2 Engine	#3 Engine
■ Serial Number	P115361	P115362	P115363
■ Hours Since New	5,124.4	5,157.4	5,180.9
■ Cycles Since New	4,333	4,341	4,370

APU

Honeywell GTCP 36-100(A) | Enrolled in MSP Gold

Serial NumberHours Since New4,330.6

Certifications

Certification Date: 2/17/2003Entry Into Service: 7/18/2003

Operated FAR 91



Avionics	Enrolled in Collins CASP
■ Electronic Flight Instrument System (EFIS)	Collins EFIS-4000
Air Data Computer (ADC)	(2) Collins ADC-850F
■ Flight Management System (FMS)	(2) Collins FMS-6100; Software Level 4.1
■ Global Positioning System (GPS)	(2) Collins GPS-4000S w/ WAAS/LPV
■ Inertial Reference System (IRS)	(2) Honeywell Laser Ref IV
■ Attitude and Heading Reference System (AHRS)	(2) Collins AHC-3000
■ Auto Pilot	Collins FCC-4009
■ VHF Communication (VHF COM)	(3) Collins VHF-422C w/ 8.33 Spacing
Satellite Communication (Satcom)	Iridium Aircell Axxess II
■ Navigation System (NAV)	(2) Collins VIR-32 w/ FM Immunity
■ High Frequency Communication (HF COM)	(2) Collins HF-9034A
Selcal	AvTech CSD-714
■ Radio Tuning Unit (RTU)	(2) Collins RTU's
■ Transponder	(2) Collins TDR-94D with ADS-B Out v2
■ Distance Measuring Equipment (DME)	(2) Collins DME-442
Automatic Direction Finder (ADF)	(2) Collins ADF-462
AFIS	Honeywell AFIS w/ SkyPrinter
■ Radio Altimeter	Collins ALT-55B
■ Weather Radar	Collins RTA-852
■ Traffic Collision Avoidance System (TCAS)	Collins TTR-4000 w/ Change 7.1
■ Enhanced Ground Prox Warning System (EGPWS)	Honeywell MK V w/ Windshear Detection
Cockpit Voice Recorder (CVR)	Honeywell
■ Emergency Locator Transmitter (ELT)	Socata 406MHz
■ Clocks	(2) Davtron M877 Chronometer



Additional Equipment/Options

- ADS-B Out (V2)
- WAAS/LPV
- TCAS 7.1
- N1 DEEC
- LED Wingtip and Landing Lights
- LED Lighting in Cabin
- Pulse Lighting System
- Recognition Light System
- Wing Ice Detection Lights
- Increased Gross Weight
- Therapeutic o2
- Rosen Cockpit Sun Visors

Connectivity

- Iridium Aircell Axxess II Phone System
- Gogo Biz ATG 4000 WiFi



Paint | August 2015 - Standard Aero (SPI)

■ White base with Ming Blue and Silver Metallic striping

Interior | August 2015 - Standard Aero (SPI) - Soft goods replaced and wood refinished

Nine (9) passenger executive interior plus 3rd crew member jump seat

- Forward cabin: Four-place club with pull out tables
- Aft cabin: Two-place club with fold out table opposite a three-place divan
- Forward galley and aft lavatory
- Airshow 500 and 14" monitor

Maintenance

Maintenance Tracking | CAMP

Inspection	Complied With	Next Due
All A/A+	Per OCIP	Per OCIP
1B	4414.6 hrs	5914.6 hrs
2B	4414.6 hrs	5914.6 hrs
3B	4414.6 hrs	6,414.0 hrs
4B		5914.6 hrs
1C	Aug 2015	Aug 2021
2C	Aug 2015	Aug 2027
3C		Aug 2021
4C		Aug 2027
Landing Gear Overhaul	Aug 2015	Aug 2027
Dry Bay Mod	Aug 2015	NA































773.935.9871 • jimdonath@donathaircraft.com • DonathAircraft.com



773.935.9871 • jimdonath@donathaircraft.com • DonathAircraft.com